

## Asante Mac OS X release notes :

All Installer will support Mac OSX version 10.1.X ,10.2.X ,10.3.X and 10.4.X

### 1- AsanteGigaNIX 1000TA card (99-00645-07)

- 1.0f1: Driver release.
- 1.0f2: Support the new leased Mac OS X (3/24/2001)
- 1.0f3: Support Asante Mac Address Only : 00:00:94
- 1.1.0: Fix multicast address register problem to support AppleTalk connection.
- 2.0.0: Support Mac OS 10.1 or later, and support sleep mode.
- 2.1.0: Support Apple Network Utility Application. This driver will load the driver when detect Asante Adapter with or without network connection.
- 2.2.0: Support ifconfig -a command. Support Mac OS 10.2.X
- 2.2.1: Support Mac OS 10.1.X and 10.2.X. Add Driver Un-installer.
- 2.2.2: Fix the driver loading problem with Mac OS Server 10.2.4 on G4-DP 867MHZ.
- 2.4.0: Support PCI-X slot in PowerMac G5. Do not use this driver in the system with 1032TA.
- 2.4.1: Support 1000TPC (99-00622-07). Support Tiger, Mac OS 10.4.X .

### 2- AsanteGigaNIX 1000SX card (99-00684-07)

- 2.0.0: Driver release.
- 2.1.0: Support Apple Network Utility Application. This driver will load the driver when detect Asante Adapter with or without network connection.
- 2.2.0: Support ifconfig -a command. Fix Authentication problem to support Mac OS 10.2.X
- 2.2.1: Fix Link report problem on Xserver 10.2.X .  
Support Mac OS 10.1.X and 10.2.X. Add Driver Un-installer.
- 2.3.0: Fix the driver loading problem with Mac OS Server 10.2.4 on XServe when connect  
to Cisco Switch.
- 2.3.1: Fix the problem with ifconfig enx down/up terminal command.  
Add remove more items in uninstaller : NetworkInterfaces.xml, Extensions.mkext,  
Extensions.kextcache
- 2.4.0: Support PCI-X slot in PowerMac G5 and Tiger MacOS 10.4.X..

### 3- AsanteGigaNIC 1064SX card (99-00511-07)

- 1.0f1: Driver release.
- 1.0f3: Support the new leased Mac OS X (3/24/2001)
- 1.1.0: Fix multicast address register problem to support AppleTalk connection.
- 2.0.0: Support Mac OS 10.1 or later, and support sleep mode.
- 2.2.0: Fix Authentication problem to support Mac OS 10.2.X
- 2.2.1: Support Mac OS 10.1.X and 10.2.X. Add Driver Un-installer.
- 2.4.0: Support PCI-X slot in PowerMac G5 and Tiger MacOS 10.4.X.

### 4- AsanteFAST 590 card (99-00590-07)

- 1.0f1: Driver release.
- 1.0f2: Support the new leased Mac OS X (3/24/2001)

- 1.0f3: Support Asante Mac Address Only : 00:00:94
- 1.1.0: Fix multicast address register problem to support AppleTalk connection.
- 2.0.0: Support Mac OS 10.1 or later, and support sleep mode.
- 2.1.0: Support Apple Network Utility Application. This driver will load the driver when detect Asante Adapter with or without network connection.
- 2.2.0: Fix Authentication problem to support Mac OS 10.2.X
- 2.2.1: Add delay in Setup Frame function to fix the problem with non-intelligent HUB v/s DSL Router on G4-733 or faster. Support Mac OS 10.1.X and 10.2.X. Add Driver Un-installer.
- 2.2.2: Fix Link Speed for PNIC1 card.
- 2.4.0: Support Tiger MacOS 10.4.X.

#### 5- AsanteFAST 690 card (99-00690-07)

- 1.0f1: Driver release.
- 1.0f2: Support the new leased Mac OS X (3/24/2001)
- 1.1.0: Fix multicast address register problem to support AppleTalk connection.
- 2.0.0: Support Mac OS 10.1 or later, and support sleep mode.
- 2.1.0: Support Apple Network Utility Application. This driver will load the driver when detect Asante Adapter with or without network connection.
- 2.2.0: Fix Authentication problem to support Mac OS 10.2.X
- 2.2.1: Add delay in Setup Frame function to fix the problem with non-intelligent HUB v/s DSL Router on G4-733 or faster. Support Mac OS 10.1.X and 10.2.X. Add Driver Un-installer.
- 2.4.0: Support Tiger MacOS 10.4.X.

#### 6- AsanteFAST 696 card (99-00696-07)

- 1.0f1: Driver release.
- 1.0f2: Support the new leased Mac OS X (3/24/2001)
- 1.1.0: Fix multicast address register problem to support AppleTalk connection.
- 2.0.0: Support Mac OS 10.1 or later, and support sleep mode.
- 2.1.0: Support Apple Network Utility Application. This driver will load the driver when detect Asante Adapter with or without network connection.
- 2.2.0: Fix Authentication problem to support Mac OS 10.2.X
- 2.2.1: Support Mac OS 10.1.X and 10.2.X. Add Driver Un-installer.
- 2.4.0: Support PCI-X slot in PowerMac G5. for Edimax 696-01(2 open cut) only , NOT for LiteON 696-00.
- 2.4.1: Support Tiger MacOS 10.4.X.

#### 7- AeroLAN AL1011-DP (99-00742-01) and AeroLAN AL1211-DP (99-00717-01) AeroLAN AL1011-DP (99-00652-01) AL1011-FR (61-20756-01)

- 1.0.0: Initial released from Open Source Community (OSC).
- 1.1.0: Support 64 bit WEP encryption. User needs to enter SSID . Add OSC License agreement.
- 1.2.0: Support 64 and 128 bit WEP encryption for AL1011 and 1211 Mac only version

PC Card.

- 1.2.1: Fix Authentication problem to support Mac OS 10.2.X
- 1.2.2: Support Mac OS 10.1.X and 10.2.X. Add Utility folder : AeroLAN\_Uninstaller to remove the driver,  
AeroLAN\_Kextload to load the driver and Touch\_AeroLAN to fix utility display problem.
- 1.2.3: AeroLAN Wireless GUI supports Apple Airport Password.
- 1.2.4: AeroLAN Wireless GUI supports Auto WEP encryption loaded when launch. Add Config\_Uninstaller
- 1.2.5: Support ShareKey WEP encryption on Apple AirPort Extreme Base Station. AeroLAN Wireless GUI supports  
convert Text to Hex . Support up to Mac OS 10.3.X only.

#### 8a- AeroLAN AL5402-XG (99-00782-01)(99-00718-01)

- 3.1.0: Apple AirPort Driver v 3.1
- 3.1.1: Apple AirPort Driver v 3.1.1
- 3.5.0: Apple AirPort Driver v 3.5.0 Support Tiger MacOS 10.4.X

#### 8b- AeroLAN AL3011-DP (99-00719-01)(99-00718-01)

- 1.0.0: Initial released from Open Source Community (OSC).
- 1.1.0: Support 64 bit WEP encryption. User needs to enter SSID . Add OSC License agreement.
- 1.2.0: Support 64 and 128 bit WEP encryption for AL3011 Mac only version PC Card.
- 1.2.1: Fix Authentication problem to support Mac OS 10.2.X
- 1.2.2: Support Mac OS 10.1.X and 10.2.X. Add Utility folder : AeroLAN\_Uninstaller to remove the driver,  
AeroLAN\_Kextload to load the driver and Touch\_AeroLAN to fix utility display problem.
- 1.2.3: AeroLAN Wireless GUI supports Apple Airport Password.
- 1.2.4: AeroLAN Wireless GUI supports Auto WEP encryption loaded when launch. Add Config\_Uninstaller .
- 1.2.5: Support ShareKey WEP encryption on Apple AirPort Extreme Base Station. AeroLAN Wireless GUI supports  
convert Text to Hex . . Support up to Mac OS 10.3.X only.

#### 9- FriendlyNet 10/100 CardBus (99-00656-07)

- 1.1.1: This driver is from Realtek driver web site (<http://www.realtek.com.tw/>) .  
Fix Authentication problem to support Mac OS 10.1.X and 10.2.X. Add Driver Un-installer.

#### 10- AsanteGigaNIX 1032TA

- 1.0: Driver release.
- 2.0.0: Support PCI-X slot in PowerMac G5. For proper operating 1000TA driver must be removed  
by 1000TA\_Uninstaller then install 1032TA driver. This driver also support 1000TA in 32 bit data only.

Support Tiger MacOS 10.4.X.

11- AsanteFAST 493 card (99-00493-07)

2.2.1: Driver release.

2.4.0: Support Tiger MacOS 10.4.X.

12- AsanteGigaNIX 2032T (99-00699-07)

\_\_a - Driver : Apple Built-in Driver

b - MacOS Support : 10.4.X